



Drum Lids, Loose

Category: Container related; facility or equipment related; forklift, pallet jack, or power lift related; product storage related - Winter 2014

Position(s) of employees/contractors:

Operator

Brief summary:

Upon arrival at facility, approx. 10 drums of waste were found with loose lids and/or rings. Drums were on skids. Driver stated that containers were tight during pickup.

List any corrective actions:

Drivers educated on container rejection, also provided with tools necessary to close drums if found loose during transport after leaving generator facility. Communicated to customer the container closure requirements. Containers evaluated and tightened to drum specifications.

Other recommendations:

Ensure drivers know right to reject loads, or request corrections before accepting waste. Ask generator or offerer to correct conditions IF they were present at the time.

Communicated to other employees, public, customers, etc.?

Incident alert posting through facilities and dispatch. Contact with customer through sales.